



Tool and Motor Control Switches

■ Brass/nickel-plated bushings Excellent for power tool and motor control switch applications.



1XWT3



1XWT5



1XWR1



1XWT1

Contact Form	Switch Function	No. of Connec.	Terminals	Mounting Hole	HP	Mfr. Model	Item No.	
Pull Chain Lever Switch, 3A @ 250V, 6A @ 120V								
SPST	On/Off	2	Wire Lead	1/2 in dia	—	774035	1XWT3	
Toggle Switch, 10A @ 250V AC, 20A @ 125V AC								
SPST	On/Off	2	Screw	0.50 in dia	3/4 hp	774019	1XWT5	
SPST	On/Off	2	Screw	0.50 in dia	3/4 hp	774011	4FRL6	
SPDT	On/Off/On	3	Quick Connect	0.50 in dia	3/4 hp	774027	4FRL7 *	
DPST	On/Off	4	Quick Connect	0.50 in dia	1 1/2 hp	774005	1XWR1	
DPDT	On/On	6	Screw	0.50 in dia	1 1/2 hp	774015	1XWR4	
DPDT	On/Off/On	6	Quick Connect	0.50 in dia	1 1/2 hp	774003	1XWR8	
DPDT	Momentary On/Off/Momentary On	6	Screw	0.50 in dia	1 1/2 hp	774000	1XWT1	
DPDT	On/Off/On	6	Screw	0.50 in dia	1 1/2 hp	774016	1XWR7	
Toggle Switch Boot, Screw-On, Pkg. of 2							774020	4FRL8

* Includes On/Off faceplate.

Panel-Mount Switches

Applications include electric motors, appliances, power tools, light fixtures, and instruments.

Note: Toggle switches have 1/2-32UNS-2A threads.



3XC60



4X216



1X692



1A823



10C582



4X087



2X464



1X878



10C560



2X488



10C569

Switch Function	Mounting Hole	AC Contact Rating	Contact Form	1-POLE Terminals	Item No.	2-POLE Terminals	Item No.
Lighted Rocker							
On/Off	0.830 in x 1.450 in	—	SPST	0.250 in Quick Connect Tab	10C587	—	—
Lighted Rocker with 120V Light							
On/Off	0.470 in x 1.070 in	10A @ 250V AC, 16A @ 125V AC	SPST	0.250 in Quick Connect Tab	1A824	—	—
On/Off	0.860 in x 1.070 in	15A @ 250V AC, 20A @ 125V AC	—	—	—	DPST	0.250 in Quick Connect Tab 3XC58
On/Off	0.830 in x 1.450 in	10A @ 250V AC, 15A @ 125V AC	SPST	0.250 in Quick Connect Tab	3XC59	—	—
On/Off	0.830 in x 1.450 in	10A @ 250V AC, 15A @ 125V AC	SPST	Screw	3XC60	—	—
On/Off	0.625 in x 1.625 in	10A @ 250V AC, 15A @ 125V AC	SPST	Screw	4X216	—	—
Lighted Rocker with 12V Light							
On/Off/On	0.830 in x 1.450 in	20A @ 12V	SPDT	0.250 in Quick Connect Tab	10C585	—	—
On/Off/On	0.830 in x 1.450 in	—	—	—	—	DPDT	0.250 in Quick Connect Tab 10C586
Miniature Push Button							
On/Off	1/2 in dia	3A @ 250V AC, 6A @ 125V AC	SPST	Screw	1X692	—	—
On/Off	1/2 in dia	10A @ 250V AC, 20A @ 125V AC	SPST	Screw	10C568	—	—
On/Mom. Off	1/2 in dia	10A @ 250V AC, 15A @ 125V AC	SPST	Screw	2X901	—	—
On/Mom. Off	1/2 in dia	3A @ 277V AC, 6A @ 125V AC	SPST	Wire Lead	10C567	—	—
Off/Mom. On	1/2 in dia	10A @ 250V AC, 15A @ 125V AC	SPST	Screw	2X894	—	—
Off/Mom. On	1/2 in dia	3A @ 250V AC, 6A @ 125V AC	SPST	Wire Lead	10C566	—	—
Polarity Reversing							
On/Off/On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	—	—	—	DPDT	Quick Connect 10C576
Reversing Toggle							
On/On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	—	—	—	DPDT	Quick Connect 10C577
Mom. On/Off/Mom. On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	—	—	—	DPDT	Quick Connect 10C580
Rocker							
On/Off	0.830 in x 1.450 in	10A @ 250V AC, 15A @ 125V AC	SPST	0.250 in Quick Connect Tab	3XC53	DPST	0.250 in Quick Connect Tab 3XC55
On/Off	0.830 in x 1.450 in	10A @ 250V AC, 15A @ 125V AC	SPST	Screw	3XC54	DPST	Screw 3XC56
On/Off	0.860 in x 1.070 in	15A @ 250V, 20A @ 125V	SPST	0.250 in Quick Connect Tab	3XC57	—	—
On/Off	0.470 in x 1.070 in	10A @ 250V AC, 15A @ 125V AC	SPST	0.250 in Quick Connect Tab	1A822	—	—
On/Off	0.470 in x 1.070 in	10A @ 250V AC, 16A @ 125V AC	SPST	0.250 in Quick Connect Tab	1A823	—	—
On/Off	0.830 in x 1.450 in	20A @ 12V	SPST	0.250 in Quick Connect Tab	10C582	—	—
Mom. On/Off/Mom. On	0.830 in x 1.450 in	20A @ 12V	—	—	—	DPDT	0.250 in Quick Connect Tab 10C583
Mom. On/Off	0.830 in x 1.450 in	10A @ 250V AC, 15A @ 125V AC	SPST	0.250 in Quick Connect Tab	10C584	—	—
Rotary							
On/Off	3/8 in	3A @ 125V AC	SPST	6 in Wire Lead	4X215	—	—
Off/On/On/On/On	1/2 in	6A @ 125V AC	SP4T	Solder Lug	4X739	—	—
Off/On/On/On	1/2 in	4A @ 125V AC	SP3T	Solder Lug	4X087	—	—
Toggle							
On/On/On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	SP3T	Quick Connect	10C575	—	—
On/On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	SPDT	Quick Connect	4X847	DPDT	Quick Connect 4X850
On/On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	—	—	—	DPDT	Quick Connect 10C570
On/On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	SPDT	Screw	2X465	DPDT	Screw 2X468
On/Off/On	0.50 in dia	10A @ 250V AC, 20A @ 125V AC	—	—	—	DPDT	Screw 10C563
On/Off/On	0.50 in dia	10A @ 250V AC, 20A @ 125V AC	—	—	—	DPDT	Quick Connect 10C551
On/Off/On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	—	—	—	DPDT	Quick Connect 10C571
On/Off/On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	SPDT	Quick Connect	4X848	DPDT	Quick Connect 4X851
On/Off/On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	SPDT	Screw	2X466	DPDT	Screw 2X469
On/Off	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	SPST	Quick Connect	4X846	DPST	Quick Connect 4X849
On/Off	0.50 in dia	10A @ 250V AC, 20A @ 125V AC	SPST	Quick Connect	10C565	DPST	Quick Connect 10C560
On/Off	0.50 in dia	16A @ 125V AC, 8A @ 250V AC	—	—	—	DPST	Screw 2X488
On/Off	0.50 in dia	3A @ 250V AC, 6A @ 125V AC	SPST	Screw	1X687	—	—
On/Off	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	SPST	Screw	2X464	DPST	Screw 2X467
On/Off	0.50 in dia	10A @ 250V AC, 20A @ 125V AC	—	—	—	DPST	Screw 10C562
On/Off	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	—	—	—	DPST	Quick Connect 10C569
On/Off	0.50 in dia	10A @ 250V AC, 20A @ 125V AC	SPST	Quick Connect	10C564	DPST	Screw 2X633
On/Off	0.50 in dia	3A @ 250V AC, 6A @ 125V AC	SPST	Wire	1X878	—	—
On/Mom. Off	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	SPST	Screw	4X201	—	—
Off/Circuit 1 On/ Circuit 1&2 Mom. On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	—	—	—	DPDT	Quick Connect 10C581
Mom. On/Off/Mom. On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	SPDT	Screw	4X203	—	—
Mom. On/Off	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	SPST	Screw	4X200	—	—
Circuit 1 On, Circuit 1&2 On, Off	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	SPDT	Quick Connect	10C579	—	—
3 Position, Circuit 1 On, Circuit 2 On, Off	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	DPDT	Quick Connect	10C578	—	—
Toggle with 12V Light							
On/Off/On	0.50 in dia	20A @ 12V	SPDT	Quick Connect	10C573	DPDT	Quick Connect 10C574
On/Off	0.50 in dia	20A @ 12V	SPST	Quick Connect	10C572	—	—
3-Pole Toggle Switches							
Contact Form	Terminals	Switch Function	Mounting Hole	AC Contact Rating	Item No.		
3PST	Screw	On/Off	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	4X208		
3PDT	Screw	On/On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	2X650		
3PDT	Screw	On/Off/On	0.50 in dia	10A @ 250V AC, 15A @ 125V AC	2X594		
Accessory For Toggle Switches							
On/Off Legend Plate, Nickel Finish							2X642