



Heavy-Duty Series 22UM02



The Wurks

Performer Edge Series 2.0

Cutting, Welding, and Heating Outfits

Medium and heavy duty outfits feature in-tip gas mixing technology and include torch mount flashback arrestors. Tag-A-Long, Toughcut, Versa-Torch, and The Wurks outfits include: torch handle, cutting attachment, cutting and welding tip, oxygen and acetylene regulators, twin welding hose, goggles, and striker.

Note: For more Consumables visit Grainger.com.

CUTTING. WELDING. HEATING

Heavy-Duty-Combo outfits cut up to 8" and weld up to 1/2" with optional tips.

Journeyman-Include cutting tip, heating and welding nozzles, 1/4" x 20-ft. T-grade hose, goggles, striker, and tip cleaner, 54RZ72 and 54RZ75 have a CGA 300 connection, which uses a right-hand female thread on the regulator. 54RZ73 and 54RZ76 have a CGA 510 connection. which uses a left-hand male thread on the

Mastar Maintenance—Lightweight, portable oxygen/acetylene outfits include a thruster air/acetylene tip and air/fuel

adapter to convert welding handle for soldering with acetylene only, and eliminate use of oxygen. All outfits include industrial-grade regulators with easy-to-adjust T-handles, WH550 rear valve welding handle, welding tip, carrying stand or rolling cart for MC or B and R or R40 tanks (tanks not included), 121/2-ft. twin hose, flint lighter, and goggles.

Medium-Duty—Cut up to 6" and weld up to 3/8" with optional tips.

The Wurks—12-pc. kit for welding, brazing, cutting, and soldering tool box. All fuel gases are mixed in tip for maximum safety. Includes tip cleaner set with 12 sizes of cleaning wires and file and all-leather welding gloves. Packed in The Wurks Box with tray.

Versa-Torch-Versatile system has nickel-plated torch handle, cutting attachment, heat tip and carrier, and reverse flow check valve. Cuts up to 3/8" and 3" with optional tips. Welds up to 1/8".

SMITH VICTOR







CUTTING. WELDING

Journeyman 450-Includes cutting tips and welding nozzle.

Performer Edge Series 2.0—Heavyduty outfits cut up to 6" and weld up to 1/4" with accessories. They include 2 regulators, cutting attachment, welding handle, welding nozzle, heating nozzle, tip cleaners, striker, T-grade hose, and goggles.

Tag-A-Long—Portable and lightweight outfits feature Series 30 regulators and reverse flow check valves. Cut up to 3/8" and 6" with optional tips. Weld up to $\frac{1}{8}$ " and $\frac{1}{2}$ " with optional tips. 6GJG1 also includes oxygen and fuel regulator, oxygen and acetylene cylinders, and lighter. Acetylene regulator not included.

CUTTING, HEATING

Heavy-Duty Series—Torch and hand torch outfits cut up to 12" with optional

Series 2.0 482W08			,					
Description Cutting, Welding, Heating	Torch Handle	Cutting Attachment	Welding Nozzles	Cutting Tips	Pressure Regulator	Brand	Mfr. Model	Item No.
leavy-Duty Series								
Heavy Duty Torch Outfit	_	SC229	_	SC12-2	40-175-540S Oxygen, CGA540 Oxygen, 40-15-510S Fuel, CGA 510 Fuel, 40-15-300S Fuel, CGA 300 Fuel	Smith Equipment	HBS-H300S	22UM0
Combo Torch And Tip Kit	WH100	MC509	MW203	MC12-1	— — — — — — — — — — — — — — — — — — —	Smith Equipment	16205	22UM0
ourneyman		CA2460+	1, 3, 5	1 Series	ESS42-15-300 Acetylene, ESS42-150-540 Oxygen	Victor	0384-2100	54RZ7
Cutting Outfit	315FC+	CA2460+	1, 3, 5	1 Series	ESS42-15-510 Acetylene, ESS42-150-540 Oxygen	Victor	0384-2101	54RZ7
ourneyman II		CA2460+	2	1 Series	ESS42-15-300 Acetylene, ESS42-150-540 Oxygen	Victor	0384-2110	54RZ7
Cutting Outfit	315FC+	CA2460+	2	1 Series	ESS42-15-510 Acetylene, ESS42-150-540 Oxygen	Victor	0384-2111	54RZ7
edium-Duty Series					30-100-540 Oyugen 30-15-300 Fuel 30-15-510			
Medium Duty Combination Outfit	WH100	MC509	MW205	MC12-0, MC12-1	30-100-540 Oxygen, 30-15-300 Fuel, 30-15-510 Fuel, CGA 300 Fuel, CGA 510 Fuel, CGA 540 Oxygen	Smith Equipment	MBA-30510	22UM
		MC509	MW205	MC12-0, MC12-1	30-100-540 Oxygen, 30-15-300 Fuel, 30-15-510 Fuel, CGA 300 Fuel, CGA 510 Fuel, CGA 540 Oxygen	Smith Equipment	MBA-30300	22UM
as Welding Outfit	WH200A	SC209	SW203	SC12-1	— — Carrott asi, carrott carrott carrott	Smith Equipment	16206	22UL
ersa-Torch lefrigeration And A/C Outfit	AW1A	AC309	LT103, LT104, LT106	MC12-00	30-100-540, 30-15-200	Smith Equipment	VT-4T	2CZK
utting, Welding	7100171	710000	21100, 21101, 21100	WOTE 00	00 100 010, 00 10 200	Omitir Equipmont	V. 1.	LULI
ourneyman 450 Cutting And Welding Outfit	315FC	CA2460	2	1 Series	SR450-540, SR460-510	Victor	0384-0807	20UJ!
erformer Edge Series 2.0	01010				·			
Gas Welding Outfit	100FC	CA1350 CA1350	(W-1) 0 (W-1) 0	3 Series 3 Series	ESS3-125-540, ESS3-15-510 ESS3-125-540, ESS3-15-300	Victor Victor	0384-2125 0384-2126	482W 482W
ig-A-Long			,		·			
Velding And Cutting Tote Jutfit W/Tanks	- CW5A	CC509P CC509P	MW203 MW203	MC12-0 MC12-0	30-100-540, 30-15-200 30-100-540 Oxygen, 30-15-200 Fuel	Smith Equipment Smith Equipment	TL-500 TL-550	2CZI 6GJ0
utting, Heating		003031	IVIVVZOJ	IVICTZ-0	30-100-340 Oxygen, 30-13-200 ruei	Officer Equipment	1L-330	uust
ledium-Duty Series Medium Duty Combination Torch Outfit	WH100	MC509		MC40-1	30-100-540, 30-50-510	Smith Equipment	MRA-205101	o o o i i i i
utting	WIIIOO	IVIOSOS		IVIO+O I	30 100 340, 30 30 310	Omitir Equipment	WIDA GOSTOLI	LLUIII
eavy-Duty Series					30-100-540 Oxygen, 30-15-300 Fuel, 30-15-510			
leavy Duty Hand Torch Toolbox Outfit		SC229	_	SC12-1	Fuel, CGA 300 Fuel, CGA 510 Fuel, CGA 540 Oxygen	Smith Equipment	HBAS-30300	22UN
leavy Duty Hallu Torch Toolbox Outili	_	SC229	_	SC12-1	30-100-540 Oxygen, 30-15-300 Fuel, 30-15-510 Fuel, CGA 300 Fuel, CGA 510 Fuel, CGA 540 Oxygen	Smith Equipment	HBAS-30510	22UN
azing, Cutting, Welding					Tuei, Gan 300 Fuei, Gan 310 Fuei, Gan 340 Oxygeii			
lastar Maintenance or B Acetylene Tank and R or R40								
Oxygen Tank, without Tanks**	WH550	CA550	Type 17#2	5-101-0	RSO/RSB2	Uniweld	KLT550-5TR	
or MC/R, without Tanks** Vith MC/R Tanks*		CA550 CA550	Type 17#2 Type 17#2	5-101-0 5-101-0	RSO/RSMC2 RSO/RSMC2	Uniweld Uniweld	KLT550-4P KLT550-4P-T	5KH2
ne Wurks			туре 17#2	3-101-0	N3U/N3IVIU2	Ulliwelu	KL1550-4F-1	JKIIZ
Vithout Tanks	WH370	CA370	Type 370#3	144#1	MR8210/MR8211	Uniweld	WURKS-A	3NY9
razing, Cutting, Heating, Welding eavy-Duty Series								
Heavy Duty Combination Torch Outfit	WH200A	SC209	SW205	SC12-1	30-100-540 Oxygen, 30-15-300 Fuel, 30-15-510 Fuel, CGA 300 Fuel, CGA 510 Fuel, CGA 540 Oxygen	Smith Equipment	HBA-30300	22UM
) W-14: O#!#		SC209	OWOOT	0010.1	30-100-540 Oxygen, 30-15-300 Fuel, 30-15-510	Oith Fit	UDA 00540	001184
Gas Welding Outfit		SC209	SW205	SC12-1 SC40-1	Fuel, CGA 300 Fuel, CGA 510 Fuel, CGA 540 Oxygen	Smith Equipment	HBA-30510	
leavy Duty Combination Torch Lp Outfit		50209		5040-1	30-100-540, 30-15-510	Smith Equipment	HBA-305 TULF	² 22UW
ircle Cutting Guide						Millor Floats: -	10000	CDITE
Cuts from 5/6" to 12" Holes mpty Fuel Cylinder						Miller Electric	16229	6PHE
uel Cylinder, Oxygen, 20 cu-ft.						Uniweld	R	2CZV
uel Cylinder, Acetylene, 10 cu-ft. ASAVER						Uniweld	MC	2CZW
Acetylene/Oxygen Gas Saver						Smith Equipment	WDW101	2CZN
Forch Valve For Use With Low Pressure (das and O	xygen				Smith Equipment	WDW103	6PHK